

EASA	AIRWORTHINESS DIRECTIVE	
	<p>AD No.: 2014-0275R1</p> <p>Date: 19 January 2015</p> <p>Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>	
<p>This AD is issued in accordance with EU 748/2012, Part 21.A.3B. In accordance with EU 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EU 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].</p>		
<p>Design Approval Holder's Name : AIRBUS</p>	<p>Type/Model designation(s) : A318, A319, A320 and A321 aeroplanes</p>	
<p>TCDS Number : EASA.A.064</p>		
<p>Foreign AD : Not applicable</p>		
<p>Revision: This AD revises EASA AD 2014-0275 dated 19 December 2014.</p>		
<p>ATA 35</p>	<p>Oxygen – Passenger Chemical Oxygen Generators – Replacement</p>	
<p>Manufacturer(s):</p>	<p>Airbus (formerly Airbus Industrie)</p>	
<p>Applicability:</p>	<p>Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers (MSN).</p>	
<p>Reason:</p>	<p>Reports have been received indicating premature ageing of certain passenger chemical oxygen generators, Part Number (P/N) 117042-XX, manufactured by B/E Aerospace. Some operators reported that when they tried to activate generators, some older units failed to activate. Given the number of failed units reported, all the generators manufactured in 1999, 2000 and 2001 must be considered unreliable.</p> <p>This condition, if not corrected, could lead to failure of the generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to passengers.</p> <p>To address this potential unsafe condition, Airbus issued Alert Operators Transmission (AOT) A35N006-14, making reference to B/E Aerospace Service Information Letter (SIL) D1019-01 (currently at Revision 1) and B/E Aerospace Service Bulletin (SB) 117042-35-001.</p> <p>Consequently, EASA issued AD 2014-0275 to require identification and replacement of the affected oxygen generators.</p> <p>Since that AD was issued, operator feedback indicated that the 30 days period for the identification of all affected generators was insufficient.</p>	

	<p>For the reason described above, this AD is revised to extend the compliance time for identification to align with the time for removal from service. This revised AD also introduces an editorial change in paragraph (2), not affecting the technical content.</p> <p>Pending the on-going investigation, this AD is still considered to be an interim action and further AD action may follow.</p>								
Effective Date:	<p>Revision 1: 19 January 2015</p> <p>Original issue: 24 December 2014</p>								
Required Action(s) and Compliance Time(s):	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within the compliance time specified in Table 1 of this AD, as applicable, identify the date of manufacture (see Appendix 1 of this AD where this is located) of each passenger oxygen generator, having a P/N as listed in Table 1 of this AD, in accordance with the instructions of Airbus AOT A35N006-14. A review of aeroplane maintenance records is acceptable to make this identification, provided those records can be relied upon for the purpose of this requirement.</p> <p>(2) Within the compliance time specified in Table 1 of this AD, as applicable, remove each affected passenger oxygen generator from service and replace it with a serviceable unit in accordance with the instructions of Airbus AOT A35N006-14 and/or, for 15 min generators, in accordance with the instructions of B/E Aerospace SB 117042-35-001.</p> <p>B/E Aerospace SIL D1019-01 Revision 1 provides instructions for the activation and the disposal of a removed passenger oxygen generator. Airbus AOT A35N006-14 (Appendix 1) includes instructions for reporting the results of the activation (including no findings) of removed units. The data gathered from those results will be analysed to determine further action(s), if any.</p> <p style="text-align: center;">Table 1 – Replacement of Passenger Oxygen Generators</p> <table border="1" data-bbox="547 1223 1426 1872"> <thead> <tr> <th data-bbox="547 1223 951 1272">P/N</th> <th data-bbox="951 1223 1426 1272">Compliance Time</th> </tr> </thead> <tbody> <tr> <td data-bbox="547 1272 951 1473"></td> <td data-bbox="951 1272 1426 1473">For units manufactured in 1999, before exceeding 15 years since date of manufacture, or within 30 days after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later</td> </tr> <tr> <td data-bbox="547 1473 951 1675"> 117042-02 (15 min - 2 masks) 117042-03 (15 min - 3 masks) 117042-04 (15 min - 4 masks) 117042-22 (22 min - 2 masks) 117042-23 (22 min - 3 masks) 117042-24 (22 min - 4 masks) </td> <td data-bbox="951 1473 1426 1675">For units manufactured in 2000, before exceeding 14,5 years since date of manufacture, or within 6 months after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later</td> </tr> <tr> <td data-bbox="547 1675 951 1872"></td> <td data-bbox="951 1675 1426 1872">For units manufactured in 2001, before exceeding 14 years since date of manufacture, or within 12 months after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later</td> </tr> </tbody> </table> <p>(3) From 24 December 2014 [the effective date of the original issue of this AD], it is allowed to install on any aeroplane a passenger oxygen generator with a P/N as listed in Table 1 of this AD, provided that the passenger oxygen generator has a manufacturing date of 2005 or later.</p>	P/N	Compliance Time		For units manufactured in 1999, before exceeding 15 years since date of manufacture, or within 30 days after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later	117042-02 (15 min - 2 masks) 117042-03 (15 min - 3 masks) 117042-04 (15 min - 4 masks) 117042-22 (22 min - 2 masks) 117042-23 (22 min - 3 masks) 117042-24 (22 min - 4 masks)	For units manufactured in 2000, before exceeding 14,5 years since date of manufacture, or within 6 months after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later		For units manufactured in 2001, before exceeding 14 years since date of manufacture, or within 12 months after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later
P/N	Compliance Time								
	For units manufactured in 1999, before exceeding 15 years since date of manufacture, or within 30 days after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later								
117042-02 (15 min - 2 masks) 117042-03 (15 min - 3 masks) 117042-04 (15 min - 4 masks) 117042-22 (22 min - 2 masks) 117042-23 (22 min - 3 masks) 117042-24 (22 min - 4 masks)	For units manufactured in 2000, before exceeding 14,5 years since date of manufacture, or within 6 months after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later								
	For units manufactured in 2001, before exceeding 14 years since date of manufacture, or within 12 months after 24 December 2014 [the effective date of the original issue of this AD], whichever occurs later								

Ref. Publications:	<p>Airbus AOT A35N006-14 dated 10 December 2014.</p> <p>B/E Aerospace SB 117042-35-001 original issue dated 10 December 2014.</p> <p>The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.</p> <p>B/E Aerospace SIL D1019-01 Revision 1, dated 03 January 2000, provides instructions for the activation and the disposal of a removed generator.</p>
Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication. 3. Enquiries regarding this AD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail ADs@easa.europa.eu. 4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – Airworthiness Office – EIAS, Fax +33 5 61 93 44 51, E-mail: account.airworth-eas@airbus.com.

SUPERSEDED

Appendix 1 – Passenger Oxygen Generator Date of Manufacture




Figure 1 – location of date (MM-YY)



Figure 2 – MFG.DATE (06-02 = June 2002) example