


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	<p>PAD No.: 15-009</p> <p>Date: 04 February 2015</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>	
Design Approval Holder's Name: EADS-CASA	Type/Model designation(s): CN-235 aeroplanes
TCDS Number:	EASA.A.186
Foreign AD:	Not applicable
Supersedure:	None
ATA 57	Wings – Aileron Fittings – Inspection
Manufacturer(s):	EADS-CASA; Construcciones Aeronáuticas S.A.(CASA)
Applicability:	CN-235, CN-235-100, CN-235-200 and CN-235-300 aeroplanes, all Models, all serial numbers.
Reason:	<p>A CN-235 operator recently reported finding, during scheduled maintenance tasks, cracks on the lugs of the control rod fittings (inboard and outboard) of the ailerons [Right Hand (RH) and Left Hand (LH) side] of two aeroplanes. At the time of finding, the two affected aeroplanes had accumulated between 16 000 and 17 000 flight hours (FH), around 6 000 flight cycles and had been in service for 20 years. Following the investigation results, it was determined that these cracks were due to stress corrosion.</p> <p>This condition, if not detected and corrected, could lead to aileron fittings failure possibly resulting in reduced control of the aeroplane.</p> <p>To address this unsafe condition and verify the integrity of the fittings, EADS-CASA (Airbus Military) issued Alert Operators Transmission (AOT) CN235-57-0001 to provide instructions for a one-time Non-Destructive (NDT) inspection of the affected fitting for cracks and corrosion.</p> <p>For the reasons described above, this AD requires a one-time NDT inspection of the affected aileron fittings and, if discrepancies are detected, accomplishment of applicable corrective action(s).</p>
Effective Date:	[TBD: 14 days after final AD issue date]

<p>Required Action(s) and Compliance Time(s):</p>	<p>Required as indicated, unless accomplished previously:</p> <p>(1) Within the compliance time as defined in the Table 1 of this AD, as applicable, accomplish an NDT inspection of the affected aileron fittings in accordance with the instructions of EADS-CASA (Airbus Military) AOT-CN235-57-0001.</p> <p style="text-align: center;">Table 1 – NDT Inspection</p> <table border="1" data-bbox="568 403 1461 577"> <tr> <th colspan="2">Compliance Time (whichever occurs later, A or B)</th></tr> <tr> <td style="text-align: center;">A</td><td>Before exceeding 8 000 FH or 10 years, whichever occurs first since aeroplane first flight.</td></tr> <tr> <td style="text-align: center;">B</td><td>Within 3 months after the effective date of this AD</td></tr> </table> <p>(2) If during the inspection as required in paragraph (1) of this AD, any crack or corrosion is detected, before next flight, contact EADS-CASA for approved repair instructions and, within the compliance time indicated in those instructions, accomplish the repair accordingly.</p>	Compliance Time (whichever occurs later, A or B)		A	Before exceeding 8 000 FH or 10 years, whichever occurs first since aeroplane first flight.	B	Within 3 months after the effective date of this AD
Compliance Time (whichever occurs later, A or B)							
A	Before exceeding 8 000 FH or 10 years, whichever occurs first since aeroplane first flight.						
B	Within 3 months after the effective date of this AD						
<p>Ref. Publications:</p>	<p>Airbus Military AOT-CN235-57-0001 Original dated 26 February 2014 or Revision 1 dated 14 March 2014.</p> <p>The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.</p>						
<p>Remarks:</p>	<ol style="list-style-type: none"> 1. This Proposed AD will be closed for consultation on 04 March 2015. 2. Enquiries regarding this PAD should be referred to the Safety Information Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: EADS CASA (Airbus Military) Services / Engineering Support e-mail: MTA.TechnicalService@military.airbus.com. Fax: +34 91 585 3127 <p>For US operators, contact alternatively: e-mail: TechnicalSupport@airbusmilitaryna.com.</p>						