


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	<p>PAD No.: 14-054</p> <p>Date: 24 March 2014</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.</p> <p>All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>	
Design Approval Holder's Name : DASSAULT AVIATION	Type/Model designation(s) : Falcon 2000EX and Falcon 900EX aeroplanes
TCDS Numbers: EASA.A.008 and EASA.A.062	
Foreign AD: Not applicable	
Supersedure: None	
ATA 57	Wings – Slat Extension Mechanical Stop Assembly – Modification
Manufacturer(s):	Dassault Aviation
Applicability:	<p>Falcon 2000EX aeroplanes, all serial numbers (S/N) on which Dassault Aviation modification (Mod) M2846 has been embodied, except those on which Dassault Aviation Mod M3678 has been embodied in production.</p> <p>Falcon 900EX aeroplanes, all S/N on which Dassault Aviation Mod M5281 has been embodied, except those on which Dassault Aviation Mod M5870 has been embodied in production.</p>
Reason:	<p>After landing, an aeroplane experienced a significant fuel leakage at the middle position of the left outboard slat. Investigations showed that the fuel spillage originated in a structural cap, which had been punctured by a broken locking pin of the slat extension mechanical stop.</p> <p>A design review revealed that the locking pin could become loose due to an incorrect installation combined with a non-fault-tolerant design.</p> <p>This condition, if not corrected, may lead to a significant fuel leak, possibly resulting in an uncontained fire.</p> <p>To address this potential unsafe condition, Dassault Aviation developed a modification of the slat extension mechanical stop assembly (Mod M3678 for F2000EX aeroplanes and Mod M5870 for F900EX aeroplanes) with the purpose to increase its robustness with regards to possible mishandling on production or during maintenance. Dassault Aviation also published Service Bulletin (SB) F2000EX-344 and SB F900EX-450, for embodiment in service of that modification.</p>

	For the reasons described above, this requires modification of the slat extension mechanical stop assembly.
Effective Date:	[TBD: 14 days after final AD issue date]
Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously: Within 9 months or 440 flight hours, whichever occurs first after the effective date of this AD, modify the slat extension mechanical stop assembly in accordance with the accomplishment instructions of Dassault Aviation SB 2000EX-344 or Dassault Aviation SB F900EX-450, as applicable to aeroplane.
Ref. Publications:	Dassault Aviation SB F2000EX-344, initial issue, dated 10 March 2014. Dassault Aviation SB F900EX-450, initial issue, dated 10 March 2014. The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.
Remarks :	<ol style="list-style-type: none"> 1. This Proposed AD will be closed for consultation on 21 April 2014. 2. Enquiries regarding this PAD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, contact your Dassault Falcon Technical Assistance: <ul style="list-style-type: none"> • For Europe, Middle East and Africa based operators: Hot Line: (33) 1 47 11 37 37 / Fax: (33) 1 47 11 89 49. • For USA, Canada and Mexico based operators: Help Desk: (1) 800-2FALCON (2325266) / Fax: (1) 201 541 4740. • All other areas: Help Desk: (1) 201 541 4747 / Fax: (1) 201 541 4740.