

Airworthiness Directive

Correction of October 12, 1978

76-136/2 MBB

Date of issue:

October 5, 1978

Affected helicopter:

German Type Certificate No. 3025.

BO 105.

All models and serial numbers.

Affected:

Gearbox supports.

Reason:

Revision of service life.

Action:

1. The limitation of service life of the gearbox supports (P/N 105-10161 and P/N 105-10162) to 4.800 hours has been extended to 6.8000 hours for the present.
2. The new service life to be entered in the BO 105 Maintenance and Overhaul Manual, Chapter 17, Airworthiness Limitations. Any new increase of service life will be reflected by later revisions of the Maintenance and Overhaul Manual by MBB.

Note:

This airworthiness directive replaces AD No. 76-136 of April 13, 1976.