

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE  
RELEASED BY THE DIRECTION GENERAL OF  
CIVIL AVIATION

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

Translation of "Consigne de Navigabilité  
Réf. 77-216-6" (B)

In case of any difficulty, reference  
should be made to the French original text.

AVIONS MARCEL DASSAULT-BREGUET AVIATION FALCON 10

AIR CONDITIONING SYSTEM - COOLING SYSTEM

Following several reported cases of FREON compressor starting resistor overheat, which may result in hazardous conditions for the aircraft, it is mandatory to install a protective thermostat on this resistor.

This modification shall be incorporated in aircraft on March 31 st 1978 at the latest, in compliance with the instructions of AMD-BA Service Bulletin n° F10 0162 which prescribes to inspect the resistor prior to installing the thermostat.

Ref. : AMD-BA Service Bulletin n° F10 0162

DATE OF EFFECTIVITY : DECEMBER 14 th, 1977

Date : 12/6/1977

Material : AVIONS MARCEL DASSAULT/  
BREGUET AVIATION FALCON 10

Reference : 77-216-6 (B)