

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 78-209(B)
In case of any difficulty, reference should be made to the French original issue.

HTL

Fire extinguisher

Bottles 11 WF P/N 336.00.005

In order to avoid damages experienced during qualification tests, HTL fire extinguisher bottles 11 WF P/N 336.00.005, are to be modified, in accordance with the HTL Service Information Letter nr 26.A.1.

Compliance required as follows :

- before bottle accumulation of 3600 flight hours, or
- within 6 months after the effective date of this A.D., which occurs latest.

Modified bottles bear the new P/N 336.00.005.1

NOTE : This type of bottles is fitted (but non necessary limited to) on some AIRBUS INDUSTRIE A300 aircraft (APU Fire extinguishing system).

Service Bulletin AIRBUS INDUSTRIE A300 26.002 refer.

Requirements of this Airworthiness Directive are covered in F.R.G. by LTA 78.306 of L.B.A.

EFFECTIVITY DATE : DECMEBER 1ST 1978