

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE  
RELEASED BY THE  
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

Translation of "Consigne de Navigabilité  
Ref. : 78-81-8(B)  
In case of any difficulty, reference  
should be made to the French original text.

AVIONS MARCEL DASSAULT-BREGUET AVIATION

FALCON 10

PASSENGER DOOR

- A - In order to provide the pilot with a permanent luminous indication of actual locking of the passengers' door control mechanism in the closed position it is mandatory to install a microswitch and connect it to "CABIN" light.
- B - To eliminate the possibility of inadvertent maneuver of the passengers' door control unlocking pushbutton, it is mandatory to install a transparent protection cup around this pushbutton.

Both installations prescribed to comply with the regulation, are outlined in AMD-BA Service Bulletin n° F10 0163, which must be incorporated in aircraft, if not already done, on July 31st 1979 at the latest.

Réf. : AMD-BA Service Bulletin n° F10-0163

EFFECTIVE ON MAY 24th 1978

Date : 5/17/1978

Material AVIONS MARCEL DASSAULT-  
BREGUET AVIATION FALCON 10

Reference : 78-81-8(B)