

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE
RELEASED BY THE
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

Translation of "Consigne de Navigabilité
Ref. : 78-202-10(B)
In case of any difficulty, reference
should be made to the French original text.

AVIONS MARCEL DASSAULT/BREGUET AVIATION
FALCON 10

FLIGHT CONTROLS - AILERON/ELEVATOR ARTHUR Q UNIT

In order to prevent, during the critical phases of take-off and landing, a possible aileron/elevator Arthur Q runaway up to the "high speed" position, it is mandatory to incorporate AMD-BA Service Bulletin n° F10 0165 within the next six months after the effective date of this "Consigne de Navigabilité".

CF. : B.S. AMD-BA F10 0165

EFFECTIVE ON : NOVEMBER 13, 1978

Date : 6/11/1978

Material : AVIONS MARCEL DASSAULT/
BREGUET AVIATION
FALCON 10

Reference : 78-202-10(B)