

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE
RELEASED BY THE
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness.

Translation of "Consigne de Navigabilité"
Réf. : 79-132-15 (B)
In case of any difficulty, reference
should be made to the French original text.

AVIONS MARCEL DASSAULT - BREGUET AVIATION
FAN JET FALCON SERIES D, E, F AIRPLANES

FIRE PROTECTION
ENGINE FIRE EXTINGUISHING FLEXIBLE LINES
IMPROVED FLEXIBILITY OF INSTALLATION

Some engine fire extinguishing hoses located between the pylon and the engine have been found damaged in service.
Such damage results in a loss of efficiency of the extinguishing system.

As a consequence a modification of installation of these lines (consisting in shortening the connection rigid tubes and replacing the hoses with new ones) in accordance with AMD-BA Service Bulletin FJF No 632 is made mandatory and must be accomplished on December 31st 1979 at the latest.

DATE OF EFFECTIVITY : JULY 25. 1979

Date : 18/7/79

Material AVIONS MARCEL DASSAULT
BREGUET AVIATION - FAN JET FALCON

Reference : 79-132-15(B)