

Airworthiness Directive

79-137 MBB

Date of issue:

March 16, 1979

Affected helicopters:

German Type Certificate No. 3025.

All Bo 105 helicopters s/n S1 through S450 inclusive, with drive shaft fairing halves P/N 105-62431 (b1 or higher) and 105-62433.

Subject:

Asbestos cloth of drive shaft fairings.

Reason:

Possible ingestion of free ends of asbestos cloth of the drive shaft fairing halves into the engines.

Action and compliance:

Unless already accomplished proceed in accordance with Service Bulletin at next 100h-Inspection after effective date of this AD.

Technical note of the manufacturer:

MBB Bo 105 Service Bulletin No. 60-43 of January 9, 1979, which becomes herewith part of this AD and may be obtained from Messrs. Messerschmitt-Bölkow-Blohm, Unternehmensbereich Drehflügler, Postfach 801140, D-8000 München 80, Western Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be entered in the helicopter's log.