

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

RELEASED BY

"DIRECTION GENERALE DE L'AVIATION CIVILE"

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 79-203-13(B)
In case of any difficulty, reference
should be made to French original issue

AVIONS MARCEL DASSAULT-BREGUET AVIATION FALCON 10

PASSENGER ACCESS DOOR

UPPER-TO-LOWER DOOR-HALF TYING LATCHES

Incidents in the field revealed a possibility of one of the two upper-to-lower door half tying latches failing to be engaged. Such defect cannot be detected once the door is closed :

- neither visually
- nor by the door indication system

Installation of stops at level of the mobile latches per the instructions of service bulletin F10 0190 eliminates this possibility of incident and is made mandatory on June 30, 1980 at the latest.

Cf. : B.S. AMD-BA F10-0190

EFFECTIVE ON OCTOBER 31, 1979

Date : October 24, 1979

Material : AVIONS MARCEL DASSAULT-
BREGUET AVIATION FALCON 10

Reference ; 79-203-13(B)