

Airworthiness Directive

79-444 MBB

Date of issue:

October 17, 1979

Affected helicopters:

German Type Certificate No. 3025

MBB Bo 105

all serial numbers up to and including S450

Subject:

Engine cowling

Reason:

Possibility of incorrect application of fire protection paint to engine cowlings.

Action and compliance:

Unless already accomplished, carry out the actions according to the Service Bulletin during the next 100 h-inspection after the effective date of this AD.

Technical publication of the manufacturer:

MBB Service Bulletin No. 60-46 August 20, 1979

which becomes herewith part of this AD and may be obtained from Messrs. Messerschmitt-Bölkow-Blohm GmbH, Unternehmensbereich Drehflügler, Postfach 80 11 40, D-8000 München 80, Western Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the helicopter's log by a licensed inspector.