

AIRWORTHINESS DIRECTIVE

83-29 Hoffmann Propellerwerk Rosenheim

Date of issue:

February 23, 1983

Affected propeller:

German Type Certificate No. 32.130/17

Variable-pitch propeller HO-V123K-()/200AH

installed on Lycoming engines ()O-540()

which are used in aerobatics, (corresponding to Category 1 of SB No. E3).

These propellers are installed in aircraft

Moravan Zlin Z50L but not limited to those.

Subject:

Pitch change fork

Reason:

Cracks in the section flank to body of the pitch change fork.

Action and compliance:

Proceed in accordance with Service Bulletin No. 3 before reaching 250 hours TSN or TSO.

Propellers which have more than 250 hours TSN or TSO, within the next 25 hours after the effective date of this AD.

Technical publication of the manufacturer:

Service Bulletin No. 3

which becomes herewith part of this AD and may be obtained from Hoffmann Propeller Rosenheim, Postbox 265, Kuepferlingstr. 9, D-8200 Rosenheim 2, W. Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the airplane's log by a licensed inspector.