

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 83-85-52(B)
In case of any difficulty, reference should be made to the French original issue.**

AIRBUS INDUSTRIE

A.300 aircraft - All models

Auxiliary Power Unit Fire Extinguisher System HTL fire extinguisher bottles

The present airworthiness directive is issued for regularization and recalls terms of telegraphic airworthiness directive sent to all airworthiness authorities concerned on May 4, 1983.

Quote

AIRBUS INDUSTRIE 6 A300 - All models

APU fire extinguisher bottles - applies to APU fire extinguisher bottles HTL P/N 33600005 as well as dash 1 and dash 2.

In order to prevent a potential risk of the bottles failing to discharge when activated, perform inspection of each fire extinguisher concerned in accordance with paragraph D (ACTION) of AIRBUS INDUSTRIE AOT/26/83/02 dated April 28, 1983 within the next 40 hours of APU time in service following receipt of this telegram, but not later than May 15, 1983.

Unquote

DATE OF EFFECTIVITY : Upon receipt of telegram dated May 04, 1983

The requirements of this Airworthiness Directive are covered in FRG by LTA No. 83-90

b.K

May 04, 1983

**AIRBUS INDUSTRIE
A300 aircraft - All models**

83-85-52(B)