

Airworthiness Directive

=====

84-178 MBB

Date of issue:

November 5, 1984

Affected helicopter:

German Type Certificate No. 3025

MBB Bo 105

All helicopters S/N S1 up to and including S350, equipped with Empennage P/N 105-31101 as well as spare parts of same P/N on stock.

Subject:

Vertical Fin

Reason:

Reinforcement of Vertical Fin in tail rotor gearbox mounting area.

Action and compliance:

Immediate accomplishment of the Service Bulletins' action is required if discrepancies have been ascertained otherwise at next suitable occasion, not later than March 31, 1985.

Technical publications of the manufacturer:

MBB Bo 105 Service Bulletin No. 30-18, Revision 2 of December 18, 1978 and

MBB Bo 105 Service Information No. 102,

which become herewith part of this AD and may be obtained from Messrs. Messerschmitt-Bölkow-Blohm, Drehflügler Abt. DS 43, Postfach 801140, D-8000 München 80, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the helicopter's log by a licensed inspector.