

Airworthiness Directive

86-106 MBB

Date of issue:

July 22, 1986

Affected helicopter:

German Type Certificate No. 3025

MBB Bo 105

Serial Numbers up to 780.

Subject:

Tailrotor gearbox, attachment bolts (P/N LN 9037-10040)

Reason:

Quality deficiency of concerned bolts requires replacement with bolts of higher strength.

Action and compliance:

Action to be accomplished in accordance with MBB Bo 105 Alert Bulletin as soon as possible, but not later than August, 31, 1986.

Technical publication of the manufacturer:

MBB Bo 105 Alert Service Bulletin No. 28 of March 27, 1986 which becomes herewith part of this AD and may be obtained from Messrs. MBB-UH, Postfach 80 11 60, D-8000 München 80, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an authorized service station and to be checked and entered in the helicopter's log by a licensed inspector.