

AIRWORTHINESS DIRECTIVE

87-106/2 MBB

Date of issue:

June 29, 1987

Affected helicopter:

German Type Certificate No. 3025 and 3049

Bo 105 all models

BK 117 all models

Subject:

Main-rotor head, hex. bolts for blade connections.

Action and compliance:

1. Proceed in accordance with action a of the Alert Service Bulletin within the next 10 flight hours after the effective date of this AD.
2. Proceed in accordance with action b of the Alert Service Bulletin within 50 flight hours after the effective date of this AD or until October 31, 1987 latest.

Technical publications of the manufacturer:

1. MBB Alert Service Bulletin ASB-Bo-10-101, Revision 1 of May 8, 1987 and Revision 2 of May 26, 1987.
2. MBB Alert Service Bulletin ASB-Bo 105LS-10-2 of May 6, 1987 and Revision 1 of May 26, 1987.
3. MBB Alert Service Bulletin ASB-MBB-BK 117-10-101 Revision 1 of May 8, 1987 and Revision 2 of May 26, 1987.

which become herewith part of this AD and may be obtained from Messrs. MBB-UH, Postfach 80 11 60, D-8000 München 80, Federal Republic of Germany.

Accomplishment and log book entry

Actions to be accomplished by an approved service station and to be checked and entered in the helicopter's log by a licensed inspector.

Note: This Airworthiness Directive cancels the AD 87-106 of May 11, 1987.