

AIRWORTHINESS DIRECTIVE

87-147 MBB

Date of issue:  
July 31, 1987

Affected helicopter:  
German Type Certificate No. 3049  
BK117A-1, A-3 and A-4, all serial numbers

Subject:  
Flight Manual

Reason:  
Procedure modification in case of chip indication in engine oil system.

Action and compliance:  
Before the next flight insert the corresponding temporary-revision  
(page 3-21) in the Flight Manual.

Technical publications of the manufacturer:  
MBB-BK117A-1 and A-3 Flight Manual temp. rev. 5, MBB-BK117A-4 temp. rev. 1,  
dated July 27, 1987

which become herewith part of this AD and may be obtained from Messrs.  
MBB-UH, Postfach 80 11 60, D-8000 München 80,  
Federal Republic of Germany

Accomplishment and log book entry:  
Action to be accomplished by a skilled person and to be entered in the  
helicopter's log.