

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 90-076-008(B) R1
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A320 aircraft

Passenger address system - CIDS

The present Airworthiness Directive applies to AIRBUS INDUSTRIE A320 series 100 and 200 aircraft equipped with a passenger address system which includes a director ref. Z010H0002110 (CIDS step 3) in position 1 without AIRBUS INDUSTRIE modification 21916.

Aircraft which have received modification 21966 (CIDS step 4) are not concerned by this Airworthiness Directive.

An incident has occurred on an aircraft in which the passengers address system was not available after engine stop.

In order to prevent the loss of the passengers address system (with CIDS step 3), the following measure is rendered mandatory on effective date of this Airworthiness Directive :

- Within next 350 flight hours, replace the director 1 by a unit ref. Z010H0002110 Amtd A in accordance with AIRBUS INDUSTRIE AOT 23/89/01 paragraph 4 dated December 27, 89.

Ref. AOT 23/89/01 dated December 27, 89

The present Rev.1 cancels and replaces the original AD 90-076-008(B) dated April 4, 1990.

EFFECTIVE DATE : APRIL 14, 1990
(same as the original AD)

e/C

January 23, 1991

AIRBUS INDUSTRIE
A320 aircraft

90-076-008(B) R1