

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 92-201-030(B)
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A320 Aircraft

Centre fuselage - Modification
Reinforce structure of belly fairing

The present Airworthiness Directive applies to A320 AIRBUS INDUSTRIE aircraft MSN 003 to 092 included.

In order to prevent initiation and propagation of damage evidenced during fatigue tests, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

Before accumulation of 12,000 flights, reinforce belly fairing structure in accordance with instructions given in AIRBUS INDUSTRIE Service Bulletin A320-53-1014.

No further action is required after accomplishment of either this Airworthiness Directive or AIRBUS INDUSTRIE Service Bulletin A320-53-1014.

Ref. : AIRBUS INDUSTRIE Service Bulletin A320-53-1014

EFFECTIVE DATE : OCTOBER 10, 1992

n/C

September 30, 1992

AIRBUS INDUSTRIE
A320 Aircraft

92-201-030(B)