

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 96-021-196(B)
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A310 Aircraft

Chafing of the electrical wire bundle

This Airworthiness Directive applies to AIRBUS INDUSTRIE A310 aircraft, all certified models and all serial numbers without application of the AIRBUS INDUSTRIE modification n° 10933.

In order to prevent the case of chafing of the electrical bundle in the right wing, which can generate short circuits and lead to the loss of the functions associated to this bundles, the following measures are rendered mandatory at the effective date of this Airworthiness Directive :

Modify the routings, attachment and protection of the wire bundle reference 626VB, 628VB and 632VB following the instructions of the AIRBUS INDUSTRIE Service bulletin A310-24-2065, before July 31, 1996.

Ref. : AIRBUS INDUSTRIE Service Bulletin A310-24-2065

EFFECTIVE DATE : FEBRUARY 10, 1996

v/JYR

January 31, 1996

AIRBUS INDUSTRIE
A310 Aircraft

96-021-196(B)