

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 2001-036(A)  
In case of any difficulty, reference should be made to the French original issue.

## ROBIN AVIATION

### ROBIN aircraft all models

Engine air intake (ATA 75)

#### 1. APPLICABILITY

This Airworthiness Directive concerns ROBIN aircraft all models all serial numbers except DR 400-500, DR 400-200R and R 2160i.

#### 2. REASON

Fault reported in service following the presence of felt obstructing carburettor air intake.

#### 3. MANDATORY ACTIONS AND COMPLIANCE

3.1. The referenced Service Bulletin instructions are rendered mandatory on the effective date of this Airworthiness Directive.

3.2. Repeat the inspection every 100 flight hours or every year, whichever occurs first.

Record application of this Airworthiness Directive in the aircraft logbook.

REF.: ROBIN AVIATION Service Bulletin No. 174 dated November 29, 2000.

**EFFECTIVE DATE : FEBRUARY 03, 2001**