

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-132(A)
In case of any difficulty, reference should be made to the French original issue.

ROBIN AVIATION

R3000, DR221 aircraft

Air intake (ATA 75)

1. APPLICABILITY

This Airworthiness Directive concerns the following ROBIN AVIATION aircraft, all serial numbers : R3000/100, R3000/120, R3000/120D, DR221, DR221B equipped with Lycoming O-235 engines.

2. REASON

The vent pipe of the carburettor tank is subject to foreign objects intrusion.

3. MANDATORY ACTIONS AND COMPLIANCE

Instructions presented by referenced Service Bulletin are mandatory within 10 flight hours following the effective date of this Airworthiness Directive.

Repeat the instructions presented by referenced Service Bulletin every 50 flight hours or every 2 months, whichever occurs first.

Record application of this AD in the aircraft logbook.

REF. : ROBIN AVIATION Service Bulletin No. 178 dated February 06, 2001

EFFECTIVE DATE : APRIL 14, 2001