

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-160-027(B)
In case of any difficulty, reference should be made to the French original issue.

DASSAULT AVIATION

FALCON 900EX aircraft

Central engine fastener (ATA 71)

APPLICABILITY:

FALCON 900EX aircraft serial numbers (S/N) from 1 to 60 inclusive except aircraft on which DASSAULT modification M2754/M2925 or Service Bulletin F900EX-103 have been embodied.

REASON:

Damage tolerance and fatigue tests performed in view of new engine fasteners certification made known a failure of hoisting plate handle and developing of cracks on mast case box, that could be resulted on loss of both central engine forward fittings.

COMPLIANCE:

Before 3750 flights since new, install reinforcements expected to overcome this situation following DASSAULT AVIATION Service Bulletin F900EX-103.

REF.: DASSAULT AVIATION Service Bulletin F900EX-103
at original issue or further approved revision.

EFFECTIVE DATE : MAY 12, 2001