

**State of Israel
Ministry of Transport
Civil Aviation Administration**

**AD 35-03-07-12R1
Date: August 27, 2003**

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft, to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** Israel Aircraft Industries Models GALAXY and Gulfstream 200 aircraft serial numbers 004-084 certificated in any category.
- SUBJECT:** Oxygen-Pilot/Copilot oxygen mask stowage box-supply line inspection and replacement.
- REASON:** To enhance reliability and to prevent the potential damage to oxygen hoses during maintenance operations, which could cause the oxygen leak.
- ACTION:**
1. Unless previously accomplished, inspect the pilot and copilot oxygen mask box supply lines for damage per Part A of the Alert Service Bulletin No. 200-35A-202, Rev.1.
 2. Unless previously accomplished, replace the existing crew oxygen mask box supply lines, with new rigid tubes per Part B of the Alert Service Bulletin No. 200-35A-202, Rev.1.
- COMPLIANCE:**
1. Compliance with Part A of the Service Bulletin is required within 50 flight hours, after the effective date of this Airworthiness Directive and every 50 flight hours thereafter until Part B of the Service Bulletin has been accomplished.
 2. Compliance with Part B of the Service Bulletin is required at the next A Check within 300 flight hours.
- EFFECTIVE DATE:** 05 September, 2003.

FOR FURTHER INFORMATION CONTACT: Mr. Boris Levin, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.
Telephone: 972-3-9774549, Fax: 972-3-9774592, e-mail: levinb@mot.gov.il