

**State of Israel
Ministry of Transport
Civil Aviation Administration**

**A D No. 35-04-09-03
Date: September 6, 2004**

**EMERGENCY
AIRWORTHINESS DIRECTIVE**

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** Israel Aircraft Industries Model **GALAXY** and Gulfstream Model **G200** aircraft, serial numbers **004 through 098**, certificated in any category.
- SUBJECT:** Replacement of Hydraflow oxygen system tubing by steel braided hoses.
- REASON:** Several cases of oxygen tubing rupture during normal service were reported, resulting in loss of supply pressure.
- ACTION:** Unless previously accomplished, replace the Hydraflow oxygen system by steel braided hoses per Gulfstream Alert Service Bulletin No. 200-35A-234.
- COMPLIANCE:** Compliance is required within 50 flight hours after the effective date of this AD.
- EFFECTIVE DATE:** This AD is effective immediately.

FOR FURTHER INFORMATION CONTACT: Mr. N. Kletshevsky, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.
Telephone: 972-3-9774-539, Fax: 972-3-9774592, e-mail kletshn@mot.gov.il