

**State of Israel  
Ministry of Transport  
Civil Aviation Administration**

**AD 53-02-08-08**

**Date: September 10, 2002**

**AIRWORTHINESS DIRECTIVE**

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** Israel Aircraft Industries Models Galaxy serial numbers 004-056 & Gulfstream 200, serial numbers 057-073, certificated in any category.
- SUBJECT:** Inspection of damage occurred to forward engine cross spar (STA 14783) P/N 4AS3177200-501.
- REASON:** To ensure the structural integrity of mentioned above assembly.
- ACTION:** Visual inspection of engine forward cross beam P/N 4AS3177200-501 for evidence of damage per Gulfstream Service Bulletin No. **200-53-128**.
- COMPLIANCE:** Within next 20 flight. If discrepancies are detected, an additional 2 flights (not exceed total 10 Flight Hours) is allowed.
- EFFECTIVE DATE:** September 15, 2002.

**FOR FURTHER INFORMATION CONTACT:** Mr. B. Keren, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.  
Telephone: 972-3-9774534, Fax: 972-3-9774592, e-mail: [kerenb@mot.gov.il](mailto:kerenb@mot.gov.il)