

**State of Israel
Ministry of Transport
Civil Aviation Administration**

**AD 71-03-03-02
Date: March 12, 2003**

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Israel Aircraft Industries Models GALAXY and Gulfstream 200 aircraft serial numbers 005-007, 058-059, 069 certificated in any category.

SUBJECT: Replacement of forward engine mount yoke attachment bolts, nuts & washers.

REASON: To prevent the possibility of failure of yoke connection bolts.

ACTION: Replace yoke attachment bolts, nuts and washers per Gulfstream Alert Service Bulletin No. 200-71A-179.

COMPLIANCE: Compliance with this AD is required within 50 flight hours.

EFFECTIVE DATE: March 22, 2003.

FOR FURTHER INFORMATION CONTACT: Mr Boaz Keren, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.
Telephone: 972-3-9774549, Fax: 972-3-9774592, e-mail: kerenb@mot.gov.il