

Airworthiness Directive

DCA/750XL/13	Aileron Inboard Hinge Attachment – Inspection and Modification
Applicability:	Model PAC 750XL aircraft, S/N 101, 102, 104 through to 120, and 122 through to 129, except aircraft with modification PAC/XL/0285 <u>already embodied</u> .
Requirement:	To prevent cracks developing in the aileron spar adjacent to the inboard hinge attachment accomplish the following: Remove both ailerons, inspect and modify the aileron spar at the inboard hinge attachment point in accordance with Pacific Aerospace Ltd Service Bulletin PACSB/XL/027.
Note:	Aileron removal, installation and rigging procedures are detailed in PAC 750XL Maintenance Manual Chapter 27-10-00.
Compliance:	Within the next 150 hours TIS or six months, whichever occurs sooner.
Effective Date:	26 April 2007