

Airworthiness Directive

DCA/750XL/8 Fuselage Roof, Station 180.85 – Inspection and Repair

Applicability: Model 750XL aircraft, S/Ns 102, 104 to 120, 122 and 125.

Requirement: To detect the possible installation of undersize rivets in the fuselage roof at STN 180.85, BL 19.67, WL 86.2 accomplish the following:

Inspect the rivets in the fuselage roof at STN 180.85, BL19.67, WL 86.2, per the accomplishment instructions in Pacific Aerospace Corporation (PAC) Service Bulletin No. PACSB/XL/019, dated 21 April 2006.

Replace undersize rivets, per the replacement instructions in PAC SB No. PACSB/XL/019.

(PACSB/XL/019 refers)

Compliance: Within the next 150 hours TIS.

Effective Date: 31 August 2006