

Airworthiness Directive

86-239 Gyroflug

Date of issue:
November 25, 1986

Affected airplane:
German Type Certificate No. 1066
SC01, SC01B, SC01B-160
all serial numbers.

Subject:
Spar attachment bolt, wing leading edge bolt.

Reason:
Material defects

Action:
Exchange of spar attachment bolts and wing leading edge bolts in accordance with Service Bulletin.

Compliance:
Before reaching 600 flight hours or 1000 landings, whichever occurs first, but not later than November 30, 1987.

Technical publication of the manufacturer:
Gyroflug Ingenieurgesellschaft mbH Service Bulletin No. 4
of September 17, 1986
which becomes herewith part of this AD.

Accomplishment and log book entry:
Action to be accomplished by the manufacturer only.