

AIRWORTHINESS DIRECTIVE

88-183 Gyroflug

Date of issue:

13. Sept. 1988

Affected airplane:

German Type Certificate No. 1066  
SC 01, SC 01 B, SC 01 B-160  
all serial numbers up to S 42

Subject:

Oil pressure hose and oil cooler hoses

Reason:

Possible faulty hose material.

Action and compliance:

Replacement of oil cooler hoses and oil pressure hose during the next annual inspection or at the latest by December 31, 1988.

Technical publication of the manufacturer:

Gyroflug Service Bulletin No. 12 of August 3, 1988 which becomes herewith part of this AD and may be obtained from Gyroflug - FFT, Gesellschaft für Flugzeuge - und Faserverbund-Technologie mbH, Flugplatz, D-7947 Mengen, Federal Republic of Germany.

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the airplane's log by a licensed inspector.