

AIRWORTHINESS DIRECTIVE

88-54 Gyroflug

Date of issue:

March 15, 1988

Affected airplane:

German Type Certificate No. 1066

SC 01, SC 01 B, SC 01 B-160

all serial numbers up to S38

Subject:

Stall warning

Reason:

Requirement for subsequent installation of a stall warning

Action and compliance:

Installation of a stall warning in accordance with the Service Bulletin until October 1, 1988.

Technical publication of the manufacturer:

Gyroflug Service Bulletin No. 7 of June 12, 1987

which becomes herewith part of this AD and may be obtained from Messrs. Gyroflug Ingenieurgesellschaft mbH, Flughafen, D-7570 Baden-Baden/Oos, Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the airplane's log by a licensed inspector.