

AIRWORTHINESS DIRECTIVE

89-19 Gyroflug

Date of issue:
March 21, 1989

Affected airplane:
German Type Certificate No. 1066
SC 01 Speed Canard
all models
serial no. up to S 46

Subject:
Fuel supply fittings

Reason:
Failure of a fitting

Action and compliance:
Within the next 25 flight hours after the effective date of this AD but not later than September 1, 1989, exchange the 6 existing fuel supply fittings with new fittings from the manufacturer.

Technical publication of the manufacturer:
Gyroflug Technical Note No. 16 of January 20, 1989

which becomes herewith part of this AD and may be obtained from Messrs. Gyroflug FFT GmbH, Postfach 85, Flugplatz, D-7947 Mengen Federal Republic of Germany

Accomplishment and log book entry:
Action to be accomplished by an approved service station and to be entered in the airplane's log by a licensed inspector.