



No.	CF-2004-23R1	1/1
Issue Date 18 July 2005		

AIRWORTHINESS DIRECTIVE

The following airworthiness directive (AD) may be applicable to an aircraft which our records indicate is registered in your name. ADs are issued pursuant to **Canadian Aviation Regulation (CAR) 593**. Pursuant to **CAR 605.84** and the further details of **CAR Standard 625, Appendix H**, the continuing airworthiness of a Canadian registered aircraft is contingent upon compliance with all applicable ADs. Failure to comply with the requirements of an AD may invalidate the flight authorization of the aircraft. Alternative means of compliance shall be applied for in accordance with **CAR 605.84** and the above-referenced **Standard**.

This AD has been issued by the Continuing Airworthiness Division (AARDG), Aircraft Certification Branch, Transport Canada, Ottawa, telephone 613 952-4357.

Number: CF-2004-23R1

Subject: Camloc Fasteners On Center Pedestal

Effective: 18 August 2005

Revision: Supersedes Airworthiness Directive CF-2004-23 issued 8 November 2004.

Applicability: Bombardier Inc. Model CL-600-2B19, serial numbers 7003 thru 7986.

Compliance: Within 5500 flight hours of the effective date of this directive, unless already accomplished.

Background: Several reports have been received of Camloc fasteners on the sidewall of the center pedestal becoming fully disengaged and interfering with an inboard rudder pedal.

This revision has been issued to amend the applicability section of this directive. No additional work is required on those aircraft that have been modified in accordance with the previous issue of this directive.

Corrective Actions:

1. As detailed in Bombardier Aerospace Service Bulletin (SB) 601R-31-030, Revision D, dated 16 June 2005, or later SB revisions approved by the Chief, Continuing Airworthiness, Transport Canada, replace the identified Camloc fasteners in the sidewall of the center pedestal with nut plate assemblies.

2. Previous replacement of the Camloc fasteners in accordance with:

- SB 601R-31-030 dated 22 June 2004;
- SB 601R-31-030, Revision A, dated 06 October 2004;
- SB 601R-31-030, Revision B, dated 04 November 2004; or
- SB 601R-31-030, Revision C, dated 15 November 2004;

also meet the requirements of this directive.

Authorization: For Minister of Transport

B. Goyaniuk.
Chief, Continuing Airworthiness

Contact: Mr. Ian McLellan, Continuing Airworthiness, Ottawa, telephone 613 952-4362, facsimile 613 996-9178 or e-mail mclelli@tc.gc.ca or any Transport Canada Centre.

Pursuant to **CAR 202.51** the registered owner of a Canadian aircraft shall, within seven days, notify the Minister in writing of any change of his or her name or address.

To request a change of address, contact the Civil Aviation Communications Centre (AARC) at Place de Ville, Ottawa, Ontario K1A 0N8, or 1-800-305-2059, or www.tc.gc.ca/civilaviation/communications/centre/address.asp