

Datum der Bekanntgabe: 10.10.1996

Muster: Dornier Luftfahrt
Dornier 328-100

AD der ausländischen Behörde:
-keine-

Geräte-Nr.:
2534

Technische Mitteilungen des Herstellers:
Dornier 328 Service Bulletin 328-31-172 vom 18.06.1996

Betroffenes Luftfahrtgerät:

Dornier Luftfahrt
Dornier 328-100
- Werk-Nrn.: 3005 bis 3065

Betrifft:

Instrumente, Anzeige/Aufzeichnung
Electric Panel 35VE und Relay Support 36VE
- evtl. Loslösung von Bauteilen

Maßnahmen:

Modifikation der betroffenen Bauteile

Fristen:

Durchführung der Maßnahmen bis spätestens 31.12.1996.

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, das es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich die sofortige Vollziehung dieser LTA anzuordnen.

Rechtsbehelfsbelehrung:

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Luftfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig einzulegen.



Luftfahrt-Bundesamt
-AD-Department-

Airworthiness Directive

*In case of any difficulty, reference should be made
to the German original issue*

96-289 Dornier Luftfahrt

Effective Date: October 10, 1996

Affected airplanes:

German Type Certificate No.: 2534

Dornier Luftfahrt

Dornier 328-100

- S/No's.: 3005 up to and including 3065

Subject:

Indicating/Recording - Modification at Electric Panel 35VE and relay support 36VE.

Reason:

Loose relay terminals caused by vibration which could lead to a possible electrical short circuit.

Action:

Modify Panel 35VE and relay support 36VE by installing new terminal studs, spacers and U-sections.

Compliance:

Action must be performed not later than December 31, 1996.

Technical publication of the manufacturer:

Dornier 328 Service Bulletin No. 328-31-172, dated June 18, 1996 becomes herewith part of this AD and may be obtained from Messrs.

Dornier Luftfahrt GmbH
P.O. Box 1103

D-82230 Wessling
Federal Republic of Germany

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log by a licensed inspector.

* * *