

**Datum der Bekanntgabe: 10.10.1996**

**Muster: Dornier Luftfahrt**  
**Dornier 328-100**

**AD der ausländischen Behörde:**  
**-keine-**

**Geräte-Nr.:**  
**2534**

**Technische Mitteilungen des Herstellers:**  
**Dornier 328 Service Bulletin No. 328-76-168 vom 06.05.1996**

**Betroffenes Luftfahrtgerät:**

Dornier Luftfahrt  
Dornier 328-100  
- Werk-Nrn.: 3005 bis 3033

**Betrifft:**

Triebwerksanlage, Seilzüge zur Triebwerksansteuerung, Rollenhalterung  
- evtl. Scheuerstellen an Seilzüge

**Maßnahmen:**

Modifikation der Rollenhalterung

**Fristen:**

**Durchführung der Maßnahmen bis spätestens 31.12.1996.**

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, das es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich die sofortige Vollziehung dieser LTA anzuordnen.

**Rechtsbehelfsbelehrung:**

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Luftfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig einzulegen.

\*\*\*



Luftfahrt-Bundesamt  
-AD-Department-

## Airworthiness Directive

*In case of any difficulty, reference should be made  
to the German original issue*

### **96-290 Dornier Luftfahrt**

Effective Date: October 10, 1996

**Affected airplanes:**

German Type Certificate No.: 2534

Daornier Luftfahrt

Dornier 328-100

- S/No's.: 3005 up to and including 3033

**Subject:**

Engine Controls - Modification of pully box.

**Reason:**

During maintenance inspection engine control cables were found to be worn in the area of the fuselage fair leads.

**Action:**

Modification of the mounting brackets of the control cable pulleys in the box for improved alignment of the control cables.

**Compliance:**

Action must be performed not later than December 31, 1996.

**Technical publication of the manufacturer:**

Dornier 328 Service Bulletin No. 328-76-168, dated May 06, 1996 becomes herewith part of this AD and may be obtained from Messrs.

Dornier Luftfahrt GmbH  
P.O. Box 1103

D-82230 Wessling  
Federal Republic of Germany

**Accomplishment and log book entry:**

Action to be accomplished by an approved service station and to be checked and entered in the log by a licensed inspector.

\* \* \*