

**Datum der Bekanntgabe: 05.12.1996**

**Muster:** Dornier  
Dornier 328

**AD der ausländischen Behörde:**  
keine

**Geräte-Nr.:**  
2534

**Technische Mitteilungen des Herstellers:**  
Dornier 328 Service Bulletin No. 328-32-183 vom 09.10.1996

**Betroffenes Luftfahrtgerät:**

Dornier  
Dornier 328-100  
- Werk-Nrn.: alle, ausgerüstet mit Hauptfahrwerk-Einfahrverriegelung P/N 22405-000-03

**Betrifft:**

Bug- und Hauptfahrwerk, Einfahrverriegelung  
- evtl. Fehlerhafte Verriegelung bei Vereisung der Einfahrverriegelung

**Maßnahmen:**

Austausch der Hauptfahrwerks-Einfahrverriegelung

**Fristen:**

Durchführung bis spätestens 31.12.1996.

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, das es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich die sofortige Vollziehung dieser LTA anzuordnen.

**Rechtsbehelfsbelehrung:**

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Luftfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig einzulegen.

\* \* \*



Luftfahrt-Bundesamt  
-AD-Department-

## Airworthiness Directive

*In case of any difficulty, reference should be made  
to the German original issue*

**96-322 Dornier**

Effective Date: December 05, 1996

**Affected airplanes:**

German Type Certificate No.: 2534

Dornier 328-100

- S/No's.: all, equipped with Main Landing Gear uplocks P/N 22405-000-03

**Subject:**

Landing Gear - Replacement of Main gear uplocks.

**Reason:**

To avoid the risk of non-locking of the main and nose landing gear due to ice accumulation on the locking roller and uplock hook.

**Action:**

Replace the main landing gear P/N 22405-000-03 uplocks with P/N 22405-000-04 uplocks.

**Compliance:**

Replacement must be performed not later than December 31, 1996.

**Technical publication of the manufacturer:**

Dornier 328 Service Bulletin No. 328-32-183, dated October 09, 1996 becomes herewith part of this AD and may be obtained from Messrs.

Faichild / Dornier  
P.O. Box 1103

D-82230 Wessling  
Federal Republic of Germany

**Accomplishment and log book entry:**

Action to be accomplished by an approved service station and to be checked and entered in the log by a licensed inspector.

\* \* \*