

**Datum der Bekanntgabe: 20.11.1997**

**Muster:** Dornier  
Dornier 328

**AD der ausländischen Behörde:**  
- keine -

**Geräte-Nr.:**  
2534

**Technische Mitteilungen des Herstellers:**  
Dornier 328 Service Bulletin Nr. 328-57-239 vom 07.07.1997

**Betroffenes Luftfahrtgerät:**

Dornier  
Dornier 328

- **Baureihen:** Dornier 328-100
- **Werk-Nrn.:** 3064 bis 3086

**Betrifft:**

Tragflächen, Landeklappenarm 2 links und rechts  
- evtl. Loslösung von Nieten am Landeklappenarm

**Maßnahmen:**

Einbau von Befestigungselementen an den Landeklappenarmen

**Fristen:**

Durchführung vor dem Erreichen von 10000 Flügen.

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, daß es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich die sofortige Vollziehung dieser LTA anzuordnen.

**Rechtsbehelfsbelehrung:**

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Luftfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig einzulegen.

\* \* \*



**Airworthiness  
Directive  
97-328**

**Luftfahrt-Bundesamt**  
Airworthiness Directive Section  
Lilienthalplatz 6  
38108 Braunschweig  
Federal Republic of Germany

**Dornier**

Effective Date: November 20, 1997

**Affected:**

Kind of aeronautical product:	Aircraft
Manufacturer:	Dornier, Wessling, Germany
Type:	Dornier 328
Models affected:	Dornier 328-100
Serial numbers affected:	3064 up to 3086
German Type Certificate No.:	2534

**Subject:**

Wings - Missed rivets on landing flap arm 2 R/H and L/H

**Reason:**

Missed rivets on landing flap arm 2 R/H and L/H must be incorporated to maintain the fatigue requirements.

**Action:**

Installation of two fasteners on flap arm.

**Compliance:**

Action must be performed before reaching 10000 flights

**Technical publication of the manufacturer:**

Dornier 328 Service Bulletin No. 328-57-239 dated July 07, 1997 which becomes herewith part of this AD and must be obtained from Messrs.:

Fairchild /Dornier  
P.O. Box 1103

D-82230 Wessling  
Phone: +49 (0) 8153-300  
Fax: +49 (0) 8153-304463

Federal Republik of Germany

**Accomplishment and log book entry:**

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.