

Datum der Bekanntgabe: 25.02.1999

Muster: Dornier
Dornier 328

AD der ausländischen Behörde:
- keine -

Geräte-Nr.:
2534

Technische Mitteilungen des Herstellers:
Dornier 328 Service Bulletin No. 328-33-271 vom 17.09.1998

Betroffenes Luftfahrtgerät:

Dornier
Dornier 328

- **Baureihen:** Dornier 328-100
- **Werk-Nrn.:** 3005 bis 3093 und 3095 bis 3111

Betrifft:

Beleuchtung, Passagier-Warnleuchten (Fasten Seat Belt / No Smoking)
- derzeit eingebaute Schaltung der Passenger Information Signs entspricht nicht den Forderungen des FAR/JAR § 25.791 (a) und (b)

Maßnahmen:

Modifikation der elektrischen Anlage gemäß den Angaben der Technischen Mitteilungen.

Fristen:

Durchführung bis spätestens 30.06.1999, falls nicht bereits geschehen.

Durch die vorgenannten Mängel ist die Lufttüchtigkeit des Luftfahrtgerätes derart beeinträchtigt, daß es nach Ablauf der genannten Fristen nur in Betrieb genommen werden darf, wenn die angeordneten Maßnahmen ordnungsgemäß durchgeführt worden sind. Im Interesse der Sicherheit des Luftverkehrs, das in diesem Fall das Interesse des Adressaten am Aufschub der angeordneten Maßnahmen überwiegt, ist es erforderlich, die sofortige Vollziehung dieser LTA anzuordnen.

Rechtsbehelfsbelehrung:

Gegen diese Verfügung kann innerhalb eines Monats nach Bekanntgabe Widerspruch eingelegt werden. Der Widerspruch ist schriftlich oder zur Niederschrift beim Luftfahrt-Bundesamt, Hermann-Blenk-Str. 26, 38108 Braunschweig einzulegen.

* * *



**Airworthiness
Directive
1999-053**

Luftfahrt-Bundesamt
Airworthiness Directive Section
Hermann-Blenk-Str. 26
38108 Braunschweig
Federal Republic of Germany

Dornier

Effective Date: February 25, 1999

Affected:

Kind of aeronautical product:	Airplane
Manufacturer:	Dornier, Wessling, Germany
Type:	Dornier 328
Models affected:	Dornier 328-100
Serial numbers affected:	3005 up to 3093 and 3095 up to 3111
German Type Certificate No.:	2534

Subject:

Lights - Passenger warning light switch modification

Reason:

The on/off switching of the „Fasten Seat Belt“ and „No Smoking“ warning lights must be independent from the reading light switch at the flight attendants panel in accordance with the FAR/JAR § 25.791 (a) and (b) requirements.

Action:

Exchange of flight attendants panel and wiring modification in accordance with the instructions given in the Dornier 328 Service Bulletin.

Compliance:

The action must be done prior June 30, 1999.

Technical publication of the manufacturer:

Dornier 328 Service Bulletin No. SB-328-33-271 dated September 17, 1998 which becomes herewith part of this AD and must be obtained from Messrs.:

Fairchild / Dornier
P.O. Box 11 03

D-82230 Wessling
Federal Republik of Germany
Phone: ++49 8153 300
Fax: ++49 8153 304463

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.

Holders of affected aircraft registered in Germany have to observe the following:

As a result of the a.m. deficiencies, the airworthiness of the aircraft is affected to such an extent that after the expiry of the a.m. dates the aircraft may be operated only after proper accomplishment of the prescribed actions. In the interest of aviation safety outweighing the interest of the receiver in a postponement of the prescribed actions, the immediate compliance with this AD is to be directed

Instructions about Available Legal Remedies:

An appeal to this notice may be raised within a period of one month following notification. Appeals must be submitted in writing or registered at the Luftfahrt-Bundesamt, Hermann-Blenk-Str. 26, 38108 Braunschweig.