



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 19-084R1

Issued: 03 July 2019

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name:

AIRBUS

Type/Model designation(s):

A310, A300-600 and A300-600ST aeroplanes

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.A.172 and EASA.A.014

Foreign AD: Not applicable

Supersedure: None

ATA 29 – Hydraulic Power – Hydraulic Reservoir Air Pressurization System Lines – Functional Tests

Manufacturer(s):

Airbus, formerly Airbus Industrie

Applicability:

Airbus A300-600 and A310 aeroplanes, all certified models, all manufacturer serial numbers (MSN); and

Airbus A300F4-608ST aeroplanes, all MSN (hereafter referred to as A300-600ST in this AD).

Definitions:

For the purpose of this AD, the following definitions apply:

The new CMR task: Variation 1.1 to A300-600 (including A300-600ST) and A310 Airworthiness Limitations Section (ALS) Part 3, Revision 1, introducing the new Certification Maintenance Requirement (CMR) task 291000-00003-1-C "Main and Auxiliary (Hydraulic Power) - Functional Check of Reservoir Air Pressurization Line for Pipe Rupture".

Note 1: Aircraft Maintenance Manual (AMM) task 29-14-00 PB 501 contains instructions to perform the new CMR task.



Reason:

The airworthiness limitations for Airbus A300-600, A300-600ST and A310 aeroplanes, which are approved by EASA, are currently defined and published in the A300-600 and A310 ALS documents. The airworthiness limitations applicable to the CMR are published in the ALS Part 3 documents.

Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2017-0203 to require accomplishment of all maintenance tasks as described in A300-600 and A310 ALS Part 3 at Revision 1.

Since that AD was issued, Airbus published Variation 1.1 to A300-600 ALS Part 3 Revision 01 and Variation 1.1 to A310 ALS Part 3 Revision 01, which introduce the new CMR task as defined in this AD. This new CMR task comprises a functional test of the reservoir air pressurization lines for pipe rupture, to detect any possible air leak.

It is expected that Airbus will issue ALS Part 3 Revision 2 for A300-600 and A310 that would incorporate this task. However, since it is not known when this ALS revision will be published, it was decided that early implementation of the new task is necessary.

For the reason described above, this AD requires repetitive pressurization tests of the reservoir air pressurization lines and, depending on findings, repair or replacement of parts.

It is expected that, when ALS Part 3 Revision 2 is issued, EASA will issue a new AD for that, in which case both EASA AD 2017-0203 and this AD will be superseded.

This PAD is revised for clarification and to amend the compliance time.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Functional Test(s):

- (1) Within 18 months after the effective date of this AD, and, thereafter, at intervals not exceeding 4 000 flight hours, accomplish the new CMR task, as defined in this AD.

Corrective Action(s):

- (2) If, during any test as required by paragraph (1) of this AD, the reservoir pressure indicators do not reach 3.5 bars (50 PSI), before next flight, identify the leak and repair or replace the affected hydraulic pipes(s) or duct(s), or the affected pressurization line. This can be accomplished in accordance with AMM task 20-23-11 or task 36-11-00, as applicable.

Terminating Action:

- (3) None.

Ref. Publications:

Airbus A300-600 (including A300-600ST) ALS Part 3 Revision 1, Variation 1.1 dated 21 February 2019.



Airbus A310 ALS Part 3 Revision 1, Variation 1.1 dated 21 February 2019.

The use of later approved revisions or variations of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 17 July 2019
2. The original issue of this PAD was posted on 21 May 2019 for consultation until 18 June 2019. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this PAD.
3. Enquiries regarding this PAD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – EIAW (Airworthiness Office)
E-mail: continued.airworthiness-wb.external@airbus.com.

