

COMMENT RESPONSE DOCUMENT

EASA PAD No. 24-039

[Published on 05 April 2024 and officially closed for comments on 03 May 2024]

Commenter 1: Eurowings Technik GmbH – Richard Stollenwerk – 29/04/2024

Comment # 1

Affected part: Emergency Location Transmitter (ELT P/N 500-12Y) bracket having Part Number (P/N) A0861

According to PAD 24-039 the unsafe condition is defined by the bracket P/N A0861 and ELT P/N 500-12Y.

Is it correct to assume that the installation location (defined by the Applicability) is also a factor as the combination of bracket and ELT might be installed on other aircraft too which are not included in PAD?

EASA response:

Airbus proofed that no unsafe condition is existing.

The PAD is withdrawn.

