

## COMMENT RESPONSE DOCUMENT

EASA PAD No. 25-017

[Published on 27 January 2025 and officially closed for comments on 24 February 2025]

**Commenter 1: AIR LLOYD Flight Services GmbH – Gerald Weidenbrueck – 28/01/2025**

### Comment # 1

With regard to the AD you have proposed I am kindly asking to check to add as statement that the Installation of the placard and the revision of the POH can be done by Pilot Owner.

This makes it much easier because of [possible] lead time and the reason that some of the aircraft are right now stored over the winter times.

### **EASA response:**

***Comment agreed. Final AD has been updated accordingly.***

