

COMMENT RESPONSE DOCUMENT

EASA PAD No.: 26-083

Published on 06 July 2026 and officially closed for comments on 03 August 2026

Commenter 1: Regio Lease – Ahmet Kursad Gul – 06/07/2026

Comment # 1

I am writing you regarding recently issued PAD No 26-083 – CFM56-7B LPT Frame.

In the below compliance requirement; it says “if TSN is unknown”, however I believe it should be “if CSN is unknown and/or if LPT Frame cycle since latest FPI/ECI inspection is unknown” to avoid any misunderstanding as well as unnecessary workload for the LPT frames with unknown CSN that have been already inspected and CSI is well recorded / kept.

- (2) If the number of total cycles accumulated by an LPT rear frame since new is unknown, before exceeding 10 engine cycles or 1 month, whichever occurs first after the effective date of this AD, inspect or replace that rear frame in accordance with the instructions of the ALS, as applicable depending on engine model and configuration.

EASA response:

Comment agreed.

The paragraph (2) of the final AD was amended accordingly.

