



## EASA Safety Information Notice

No.: 2008-06

Issued: 06 February 2008

**Subject:** Unapproved Parts – Installed in Honeywell IVA-81A TCAS II Vertical Speed Indicators

**Ref. Publication:** FAA Special Airworthiness Information Bulletin (SAIB) NM-08-12.

**Introduction:** This Safety Information Notice (SIN) refers to FAA SAIB NM-08-12 (attached to this document as pages 2 and 3) and advises aircraft owners, operators, maintenance organisations and parts distributors, to inspect Honeywell IVA-81A Traffic Alert and Collision Avoidance System (TCAS II) Traffic Advisory/Vertical Speed Indicators (TCAS/IVSI) for unapproved parts, and to bring them back to conformance with type design.

**Applicability:** Individual Honeywell IVA-81A units as identified in the attached SAIB; these are known to be installed on, but not limited to, transport category aircraft.

**Recommendation:** This Safety Information Notice is for information only.

**Contact:** For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.  
E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).