



EASA Safety Information Notice

No.: 2008-15

Issued: 05 March 2008

Subject: Improper Maintenance Performed on Aircraft Appliances

Ref. Publication: FAA Unapproved Parts Notification (UPN) No. 2007-00045.

Introduction: The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 and 3 of this notice) as a result of an investigation that revealed that, despite improper maintenance, engine accessory units applicable to Boeing aircraft, Royal Inventum water heaters, and Driessen hot cups were approved for return to service.

Applicability: Any aircraft and/or engines, as applicable, that have appliances installed that were subject to the improper maintenance as referenced in the FAA UPN.

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu.