



EASA Safety Information Notice

No.: 2008-25

Issued: 01 April 2008

Subject: Main Landing Gear (MLG) truck beams that have been improperly maintained and returned to service

Ref. Publication: FAA Unapproved Parts Notification (UPN) No. 2008-S20080110024.

Introduction: The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 through 12 of this notice) as a result of an investigation that revealed that certain MLG truck beams used on large aircraft have been improperly maintained and returned to service, contrary to regulations.

Applicability: MLG truck beams held as spares and identified in the attached FAA UPN; and any Boeing 707, 747, 757 and 767 aircraft which have MLG truck beams, as identified in the attached FAA UPN, installed.

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.
E-mail: ADs@easa.europa.eu .