



EASA Safety Information Notice

No.: 2008-31

Issued: 07 April 2008

Subject: Honeywell Model IVA-81A TCAS Display Indicators that have been improperly overhauled and returned to service

Ref. Publication: FAA Unapproved Parts Notification (UPN) No. 2008-200600159.

Introduction: The Federal Aviation Administration (FAA) has published the referenced UPN (attached as pages 2 and 3 of this notice) as a result of an investigation that revealed that certain Honeywell Model IVA-81A TCAS display indicators have been improperly overhauled and returned to service, contrary to regulations.

Note: On 30 January 2008, the FAA published Special Airworthiness Information Bulletin (SAIB) NM-08-12 for this same subject, which was adopted by the Agency and published as EASA SIN 2008-06 dated 06 February 2008.

Applicability: Honeywell Model IVA-81A TCAS display indicators held as spares and identified in the attached FAA UPN; and any Transport Category aircraft which have Honeywell Model IVA-81A TCAS display indicators, as identified in the attached FAA UPN, installed.

Recommendation: This Safety Information Notice is for information only.

Contact: For further information contact the Airworthiness Directives, Safety Management and Research Section, Certification Directorate, EASA.
E-mail: ADs@easa.europa.eu .