



Safety Information Bulletin

Airworthiness

SIB No.: 2015-21

Issued: 09 October 2015

Subject: Notification of Unapproved Parts

Ref. Publications:

None.

Applicability:

Iacobucci HF Aerospace Spa (IHFA) Trolleys, having part number (P/N) MK667-44, P/N MK667-4401, P/N MK667-4402, P/N MK708-4401, P/N MK708-4402, P/N MK708-4403, P/N MK708-4404, and P/N MK708-4405.

These trolleys are known to be installed on, but not limited to, Airbus A380 and Boeing 777 aeroplanes.

Description:

Ente Nazionale Aviazione Civile (ENAC), the national airworthiness authority of Italy, informed EASA about unapproved spare parts, manufactured and sold by Iacobucci Equipment and Service (IES) Srl and intended, for installation on, but not limited to, trolleys as identified in the Applicability of this SIB. IES is located in Località Colle Baiocco snc, 03013 Ferentino, Italy, and does not hold Production Organisation Approval (POA) issued under Regulation (EU) [748/2012](#), Annex I, Part 21. IES is not related with the manufacturer of the trolleys, Iacobucci HF Aerospace (IHFA) Spa, which holds a Part 21 POA (approval reference: IT.21G.0037).

Before IHFA, the following POA organisations were approved by ENAC for manufacturing the part numbers listed in the Applicability of this SIB and relevant spare parts: Iacobucci Spa until 10 November 2010, Iacobucci ATS Spa until 10 November 2014. Both organisations had approval reference IT.21G.0023. On 10 November 2014 Iacobucci ATS Spa was incorporated into the Iacobucci HF Aerospace Spa IT.21G.0037.

A list of the unapproved spare parts includes: pedal brakes, pedal support, pin, stop arrester, hinge, ball latch, spring, latch top late, door assembly, plate bottom caster locker, solid reinforced extrusion lock, top end rear, tag, bolts, bracket handle.

Table 1 of this SIB provides a partial list of these parts; other unapproved parts may have been also sold by IES.

At this time, the safety concern described in this SIB is not considered to be an unsafe condition that would warrant Airworthiness Directive (AD) action under Regulation (EU) [748/2012](#), Part 21.A.3B.

Recommendation(s):

Owners, operators, maintenance organisations and distributors are encouraged to investigate whether parts manufactured and/or sold by IES are held in stock, or are installed on IHFA trolleys. If any suspected part is found installed on a trolley or held in stock, the part or the trolley should be quarantined to prevent its installation or utilization, until the safety of the part(s) can be determined.

This is information only. Recommendations are not mandatory.



Table 1 – Affected spare parts

Part Number	Description	Part Number	Description
MK667400AV01	Door Assembly	MK17810319	Pin
FT01911012	Pin, Upper Table	MK17810320	Spacer
FT01912023	Ball	MK17810322	Pin, Pedal
FT02111011	Pin	MK18010303	Pedal - green brake
FT021130	Caster	MK18010304	Pedal - red brake
FT021140	Caster with brake	MK18010307	Linkage
FT043160	Bolt	MK18010316	Spring
FT04850007	Seal	MK19010002	Support, Caster
IM1610303	Guide	MK19610301	Support, Pedal
IM1610308	Spacer	MK19610302	Support, Pedal
MK1110411	Support	MK19650003	Bracket, Handle
MK15010004	Spacer	MK24810305A	Pedal, brake red
MK15010005	Spacer	MK24810306A	Pedal, brake green
MK15010303	Support	MK24810308	Support
MK15010304	Retainer, spring	MK24850006	Tongue
MK15110307A	Pedal SX	MK24850007	Plate, Cover
MK15110308A	Pedal DX	MK248502	Pin, Command
MK15110309	Spring	MK24852001B	Hinge
MK17810312	Stop, Arrestor	MK24853011B	Spring
MK17810313	Pin, Brake Pedal	MK27950005-1	Lever
MK17810317	Spring	MK667500AV01	Door Assembly
MK17810318	Spring	MK708500AV03	Door Assembly

Contact(s):

For further information contact the EASA Safety Information Section, Certification Directorate.

E-mail: ADs@easa.europa.eu.

Iacobucci HF Aerospace Spa, Strada SC ASI 1/S nn.16-18, 03013 Ferentino, Italy

Web site: www.iacobucci.aero.

E-mail: customersupport@iacobucci.aero.

This is information only. Recommendations are not mandatory.



An agency of the European Union