

File

TRANSLATION

AD 71-42-1 dated 13-5-71

NOT YET APPROV. ACC 15/9/71

AEROSPATIALE LAMA SA-315B HELICOPTERS

MAIN ROTOR HUB

In order to ascertain of the correct installation of the drag hinge pin on the main rotor hubs it is mandatory to inspect this installation

- upon receipt of this AD on helicopters presenting a vibration phenomenon of 1 ~~10~~
- not later than 31 May 1971
- before putting the spare hubs into service (new or overhauled).

This should  
Cover FAA  
CERTIFIED A/C.

See Aerospatiale Alouette Service Bulletin No. 01-25.

71-42-1